

REQUEST FOR INSPECTION

CALL DATE: 8/31/23 TIME _____ : _____ AM / PM
 PROPERTY ADDRESS: 3 Farnham Park PERMIT NUMBER: # 20026

INSPECTOR

Bob Baldwin Jason Bienek Cary Moran Jose Gomez City Engineer Colc K

Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous

CONTRACTOR NAME: Rigo Fernandez
 CONTACT PHONE/EMAIL: # 282-541-6706
 INSPECTOR COMMENTS: The view con. Group.

PASS **FAIL**

DATE: 8/31/23
 TIME: 11:50
 INSPECTOR: Colc K.

Re-Inspection Fee Required

Late A.M. please "For Pool and partial downspouts" - Pipes along S side dig up, re-inspec
- Verify turf around pool OK.
- Pipes through curb need to be placed per detail, showed in. Appears current spacing does not allow for downspout.
- RFFF not ~~was~~ placed around perimeter or at inlets as required.
- Recommend filling inlet bottoms w/ gravel.