

REQUEST FOR INSPECTION

CALL DATE: 4/13/2022 TIME: _____ : _____ AM / PM

PROPERTY ADDRESS: 11515 Way Home / Memorial Drive PERMIT NUMBER: _____

INSPECTION INFORMATION

INSPECTOR: Bob Baldwin Jason Bienek Cary Moran City Engineer Walter Wesley

Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)
Stair Compliance	Electrical Cover	Sewer Disconnect
Framing Only	Electrical Ditch Cover	Plumbing Water Line
Frame Cover	Electrical TCI	Plumbing Sewer Line
Poly Seal	Electrical Reconnect	Plumbing Ground
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)
Brick Tie	Pool Electrical Final	Plumbing Cover
Stucco Lathe	Electrical Final	Plumbing Final
Building Final	Temporary Drainage	Pool Plumbing Cover
Irrigation Trench / Tree Final	Drainage Partial	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Cover	Plumbing Pool Final
Driveway Final	Drainage Final	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous

CONTRACTOR NAME: Dexter Williams w/

CONTACT PHONE/EMAIL: Dennis Williams (781) 530-3737

INSPECTOR COMMENTS: partial ~~final~~ drainage cover
re-inspection

PASS	FAIL
DATE: <u>4/14/22</u>	
TIME: <u>11:00</u>	
INSPECTOR: <u>Alan Crosby</u>	

781-530-0427

Recommended raising inlet directly upstream of L2
on drainage plan to facilitate smooth grading
to inlet

Re-Inspection Fee Required

REQUEST FOR INSPECTION

CALL DATE: 4/7/2022 TIME _____ : _____ AM / PM
 PROPERTY ADDRESS: 11513 Wayman (Memorandum) PERMIT NUMBER: P# 17805

INSPECTION INFORMATION

INSPECTOR: Bob Baldwin Jason Bienek Cary Moran City Engineer Clawn Croley ^{w/ HDR}

Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel - Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping - Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)
Stair Compliance	Electrical Cover	Sewer Disconnect
Framing Only	Electrical Ditch Cover	Plumbing Water Line
Frame Cover	Electrical TCI	Plumbing Sewer Line
Poly Seal	Electrical Reconnect	Plumbing Ground
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)
Brick Tie	Pool Electrical Final	Plumbing Cover
Stucco Lathe	Electrical Final	Plumbing Final
Building Final	Temporary Drainage	Pool Plumbing Cover
Irrigation Trench / Tree Final	<u>Drainage Partial</u>	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Cover	Plumbing Pool Final
Driveway Final	Drainage Final	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous

CONTRACTOR NAME: Dennis Williams & Co. ^{Tyler Williams}

CONTACT PHONE/EMAIL: (281) 850-6613 (p)

INSPECTOR COMMENTS: ~~partial drain~~ partial drain cover

PASS FAIL

DATE: 4/7/22

TIME: 12:00

INSPECTOR: Clawn Croley

- Need to ~~seal~~ connection of 15" pvc pipe to inlet on north side of property (L8 on drainage plan). Connection does not appear to be water-tight at top of pipe
- Downstream inlets on east and south sides of property appear to be covered and will not capture storm water as intended on drainage plan
- Inlet protection barriers need to be installed per temp. drainage plan
- Still need to inspect restrictor pipe at outfall
- All other pipes can be covered.

Re-Inspection Fee Required