REQUEST FOR INSPECTION

CALL DATE: 11-15-22 TIME 2: 30 AM-PM PROPERTY ADDRESS: 11325 (oreenbay PERMIT NUMBER: 17812		
INSPECTOR ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer		
	Consumbry Consumbry Shool Red	Machanical Cover
Demolition Temperary Tree Protection	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Flectrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous
CONTRACTOR NAME: Statement purch of the stan PASS FAIL		
CONTACT PHONE/EMAIL: DAISY DATE: 11-15-22		DATE: 11-15-22
INSPECTOR COMMENTS: 7/3-47/6-0429		TIME: 2:30
		INSPECTOR: TASON
Phy master than the Re-Inspection Fee Required		
Closet island need to Remik floor Covering		
MISSing Plater attac. Missing Pluge left		
and Bight of Bitchen Sink, Vaporeson Need		
plug by prell windows Within 18"		
Med to what yo both Recess trim Missing		
VAnily plug by Bight Sinil in Bunk Bath.		