REQUEST FOR INSPECTION		
CALL DATE: 3/28/23 TIME : AM / PM		
PROPERTY ADDRESS: 11202 Smithdele Rd PERMIT NUMBER:# 19638		
<u>INSPECTOR</u> (Neal		
□ Bob Baldwin □ Jason Bienek □ Cary Moran □ Jose Gomez ☑ City Engineer \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		
Demolition	Generator Concrete Steel Pad	Mechanical Cover
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal
Piers	Fence Final	Mechanical Box Seal
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)
Stair Compliance	Electrical T-Pole	Sewer Disconnect
Framing Only	Electrical Cover	Plumbing Water Line
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line
Poly Seal	Electrical TCI	Plumbing Ground
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generator
Brick Tie	Pool Electrical Cover	Plumbing Cover
Stucco Lathe	Pool Electrical Final	Plumbing Final
Building Final	Electrical Final	Pool Plumbing Cover
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap
Driveway / Steel	Drainage Partial	Plumbing Pool Final
Driveway Final	Drainage Cover	Water Heater Final
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous
CONTRACTOR NAME: Austen	W Thomason	PASS FAIL
CONTACT PHONE/EMAIL: # 936 - 525 - 0866		DATE: 3/28/23
INSPECTOR COMMENTS: Deanco inc		TIME: /iOO
		INSPECTOR: (de 1/1/2)
Reinforced Filter Fabric Fame Re-Inspection Fee Required		
prost be placed along all primiters as shown on		
Johns.		
Inlet protection Burrier (fitter tabric) must be plured on		

All & temporary drainage pipe most be in place for pass.