REQUEST FOR INSPECTION

CALL DATE: 2-14-22 TIME 10:55 AM/PM PROPERTY ADDRESS: 11219 Hermisa 4 PERMIT NUMBER: 17147				
INSPECTION INFORMATION INSPECTOR: Bob Baldwi Jason Bienek City Engineer				
Demolition	Generator Concrete Steel Pad	Mechanical Cover		
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood		
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal		
Piers	Fence Final	Mechanical Box Seal		
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up		
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final		
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out		
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)		
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)		
Stair Compliance	Electrical Cover	Sewer Disconnect		
Framing Only	Electrical Ditch Cover	Plumbing Water Line		
Frame Cover	Electrical TCI	Plumbing Sewer Line		
Poly Seal	Electrical Reconnect	Plumbing Ground		
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board		
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)		
Brick Tie	Pool Electrical Final	Plumbing Cover		
Stucco Lathe	Electrical Final	Plumbing Final		
Building Final	Temporary Drainage	Pool Plumbing Cover		
Irrigation Trench / Tree Final	Drainage Partial	Pool Plumbing Vacuum Breaker, P-Trap		
Driveway / Steel	Drainage Cover	Plumbing Pool Final		
Driveway Final	Drainage Final	Water Heater Final		
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final		
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous		
CONTRACTOR NAME:	Journa Home	PASS FAIL		
CONTACT PHONE/EMAIL: June	1015-21/2-MUL	DATE: 2-14-22		
INSPECTOR COMMENTS:	TI BILL CATE	TIME: 10:55		
INSPECTOR CONTINENTS.		INSPECTOR: 7450n		
Partial- Inside ONLY				
TITION ANNUE (TIME)				
	The state of the s			

Re-Inspection Fee Required

REQUEST FOR INSPECTION

CALL DATE: 2-8-22 TIME 9:00 AM PM				
CALL DATE: 2-8-22 TIME 9:90 AM PM PROPERTY ADDRESS: 11219 Hermosa PERMIT NUMBER: 17147				
	INSPECTION INFORMATION			
INSPECTOR: ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ City Engineer				
Demolition	Generator Concrete Steel Pad	Mechanical Cover		
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood		
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal		
Piers	Fence Final	Mechanical Box Seal		
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up		
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final		
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out		
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)		
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)		
Stair Compliance	Electrical Cover	Sewer Disconnect		
Framing Only	Electrical Ditch Cover	Plumbing Water Line		
Frame Cover	Electrical TCI	Plumbing Sewer Line		
Poly Seal	Electrical Reconnect	Plumbing Ground		
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board		
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GTO- House)		
Brick Tie	Pool Electrical Final	Plumbing Cover		
Stucco Lathe	Electrical Final	Plumbing Final		
Building Final	Temporary Drainage	Pool Plumbing Cover		
Irrigation Irench / Tree Final	Drainage Partial	Pool Plumbing Vacuum Breaker, P-Trap		
Driveway / Steel	Drainage Cover	Plumbing Pool Final		
Driveway Final	Drainage Final	Water Heater Final		
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final		
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous		
CONTRACTOR NAME:	lancorny Del	PASS FAIL		
CONTACT PHONE/EMAIL:	90	DATE: 2-8-22		
INSPECTOR COMMENTS: 915	-216-0046	TIME: 9:00		
Inside only		INSPECTOR: Juston		
Week to lan long line to frienit				
Laprage Passenger Doon to House must be				
Left Clasina				
Light Suit h by Brack Doon Cover				
lows shif off Access of Frence				
Re-Inspection Fee Required				

REQUEST FOR INSPECTION

	REQUEST FOR INST ECTION			
CALL DATE: 2-3-22 TIME 10: 10 (AM)/ PM PROPERTY ADDRESS: 11219 HELEMOSA CT PERMIT NUMBER: 17147				
PROPERTY ADDRESS: 11219 HERMOSA CT PERMIT NUMBER: 17147				
1970.9	INSPECTION INFORMATION			
INSPECTOR: Bob Bald Dason Bienek Gary Moran City Engineer				
Demolition	Generator Concrete Steel Pad	Mechanical Cover		
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood		
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal		
Piers	Fence Final	Mechanical Box Seal		
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up		
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final		
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out		
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)		
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)		
Stair Compliance	Electrical Cover	Sewer Disconnect		
Framing Only	Electrical Ditch Cover	Plumbing Water Line		
Frame Cover	Electrical TCI	Plumbing Sewer Line		
Poly Seal	Electrical Reconnect	Plumbing Ground		
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board		
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)		
Brick Tie	Pool Electrical Final	Plumbing Cover		
Stucco Lathe	Electrical Final	Plumbing Final		
Building Final	Temporary Drainage	Pool Plumbing Cover		
Irrigation Trench / Tree Final	Drainage Partial	Pool Plumbing Vacuum Breaker, P-Trap		
Driveway / Steel	Drainage Cover	Plumbing Pool Final		
Driveway Final	Drainage Final	Water Heater Final		
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final		
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous		
CONTRACTOR NAME: Ashin	n leron Homes	PASS FAIL		
CONTACT PHONE/EMAIL: Juan 915-216-0046		DATE: 2-3-22		
INSPECTOR COMMENTS:		TIME: 10.10		
No Access	L. Tor do	INSPECTOR: JASON		
110 110 TO 1815 Ide				