## **REQUEST FOR INSPECTION**

CALL DATE: 10/13/2022	TIME	: (AM) / PM	
PROPERTY ADDRESS: 1/219 Claymore	B. S. Fred .	PERMIT NUMBER:# 19144	-

## **INSPECTION INFORMATION**

4 -		WICOLE	
Demolition	Generator Concrete Steel Pad	Mechanical Cover	
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood	
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal	
Piers	Fence Final	Mechanical Box Seal	
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up	
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final	
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out	
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)	
Ridge Height - Verification	Electrical T-Pole	Mechanical Final (Wine Room)	
Stair Compliance	Electrical Cover	Sewer Disconnect	
Framing Only	Electrical Ditch Cover	Plumbing Water Line	
Frame Cover	Electrical TCI	Plumbing Sewer Line	
Poly Seal	Electrical Reconnect	Plumbing Ground	
Insulation	Pool Electrical Underground	Plumbing Shower Pan/Wall Board	
Wall Board Interior	Pool Electrical Cover	Plumbing Gas (GT0- House)	
Brick Tie	Pool Electrical Final	Plumbing Cover	
Stucco Lathe	Electrical Final	Plumbing Final	
Building Final	Temporary Drainage	Pool Plumbing Cover	
Irrigation Trench / Tree Final	Drainage Partial	Pool Plumbing Vacuum Breaker, P-Trap	
Driveway / Steel	Drainage Cover	Plumbing Pool Final	
Driveway Final	Drainage Final	Water Heater Final	
Sidewalk/Flatwork/Pavers Steel	Fire Sprinkler Cover	Irrigation Final	
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Final	Other/Miscellaneous	
CONTRACTOR NAME: Charles Chapman(counthian Contraction		PASS FAIL	
CONTACT PHONE/EMAIL: # 713.516.4947		DATE: 10/13/2022	
INSPECTOR COMMENTS:		TIME: //:/5 AM	
Require REF Reinforced Filter		INSPECTOR: Cole 1	
Fabric Fince ground perimeter of lot and			
around pack inlet.			
Grate and inlet in NE torner of lot appears			
to be broken			
Missing Inlets #8 and #9 ground pool shown			
on deurage plan.			