REQUEST FOR INSPECTION CALL DATE: 11/3/02 TIME : AM/PM PROPERTY ADDRESS: 420 Chaple wood PERMIT NUMBER: **INSPECTOR** ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer _ Demolition Generator Concrete Steel Pad Mechanical Cover Temporary Tree Protection Generator Final - Operative Mechanical Vent Hood Fencing **Pre-Construction Site** Fence Post Hole Mechanical Grill Seal **Piers** Fence Final Mechanical Box Seal **Foundation Repair** Pool Stake Out & Pool Doc Box Set Up Mechanical Air Make Up Foundation Steel - Survey Verified Deck Steel / Pool Steel Mechanical Final Hurricane Strapping - Exterior Wall Deck Final / Pool Final Mechanical Change Out Wall Board Exterior **Roof Final** Mechanical Cover (Wine Room) Ridge Height - Verification Synthetic Turf Mechanical Final (Wine Room) Stair Compliance **Electrical T-Pole** Sewer Disconnect Framing Only **Electrical Cover Plumbing Water Line** Frame Cover **Electrical Ditch Cover Plumbing Sewer Line Poly Seal Electrical TCI Plumbing Ground** Insulation **Electrical Reconnect** Plumbing Shower Pan/Wall Board Wall Board Interior Pool Electrical Underground Plumb Gas: House / Pool / Generator **Brick Tie** Pool Electrical Cover **Plumbing Cover** Stucco Lathe Pool Electrical Final **Plumbing Final Building Final Electrical Final Pool Plumbing Cover** Tree Final **Temporary Drainage** Pool Plumbing Vacuum Breaker, P-Trap Driveway / Steel **Drainage Partial Plumbing Pool Final Driveway Final Drainage Cover** Water Heater Final Sidewalk/Flatwork/Pavers Steel Drainage Final Irrigation Trench / Final Sidewalk/Flatwork/Paver Final Fire Sprinkler Cover / Final Other/Miscellaneous CONTRACTOR NAME: Chans Stee) PASS **FAIL** DATE: CONTACT PHONE/EMAIL: 15 781 - 408 3402 TIME: INSPECTOR COMMENTS: Land Onta INSPECTOR: Re-Inspection Fee Required