	REQUEST FOR INSPECTION		
CALL DATE: 3-16-23	TIME	AM	
PROPERTY ADDRESS: 1/207	Sm. Hadelo KD, PER	ANT ALLIA ADED: 1979	
1		WIII NOWBER: / / / / / /	
Rob Roldwin D Josep Bionels J	INSPECTOR		
☑ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer			
Demolition	Generator Concrete Steel Pad	Mechanical Cover	
Temporary Tree Protection Fencing	Generator Final - Operative	Mechanical Vent Hood	
Pre-Construction Site	Fence Post Hole	Mechanical Grill Seal	
Piers	Fence Final	Mechanical Box Seal	
Foundation Repair	Pool Stake Out & Pool Doc Box Set Up	Mechanical Air Make Up	
Foundation Steel – Survey Verified	Deck Steel / Pool Steel	Mechanical Final	
Hurricane Strapping – Exterior Wall	Deck Final / Pool Final	Mechanical Change Out	
Wall Board Exterior	Roof Final	Mechanical Cover (Wine Room)	
Ridge Height - Verification	Synthetic Turf	Mechanical Final (Wine Room)	
Stair Compliance	Electrical T-Pole	Sewer Disconnect	
Framing Only	Electrical Cover	Plumbing Water Line	
Frame Cover	Electrical Ditch Cover	Plumbing Sewer Line	
Poly Seal	Electrical TCI	Plumbing Ground	
Insulation	Electrical Reconnect	Plumbing Shower Pan/Wall Board	
Wall Board Interior	Pool Electrical Underground	Plumb Gas: House / Pool / Generato	
Brick Tie	Pool Electrical Cover	Plumbing Cover	
Stucco Lathe	Pool Electrical Final	Plumbing Final	
Building Final	Electrical Final	Pool Plumbing Cover	
Tree Final	Temporary Drainage	Pool Plumbing Vacuum Breaker, P-Trap	
Driveway / Steel	Drainage Partial	Plumbing Pool Final	
Driveway Final	Drainage Cover	Water Heater Final	
Sidewalk/Flatwork/Pavers Steel	Drainage Final	Irrigation Trench / Final	
Sidewalk/Flatwork/Paver Final	Fire Sprinkler Cover / Final	Other/Miscellaneous	
CONTRACTOR NAME: Start	key Humbins	PASS FAIL	
CONTACT PHONE/EMAIL:	-472-3141	DATE: 3-16-23	
INSPECTOR COMMENTS: Degin	o, Weste, Vent Copper	TIME: J. 30	
		INSPECTOR: 1364 3330	
Avea t	Kitchen Area	Re-Inspection Fee Required	
	,		
- HA 712 HEAD 1324			
720	0 11000	6101	
	All the Control of th		