REQUEST FOR INSPECTION CALL DATE: 7/3/23 TIME 8:24 AM/PM PROPERTY ADDRESS: 367 Tynebydge LN PERMIT NUMBER: #19968 **INSPECTOR** ☐ Bob Baldwin ☐ Jason Bienek ☐ Cary Moran ☐ Jose Gomez ☐ City Engineer ___ Demolition **Generator Concrete Steel Pad Mechanical Cover Temporary Tree Protection Generator Final - Operative Mechanical Vent Hood** Fencing **Pre-Construction Site Fence Post Hole** Mechanical Grill Seal Fence Final **Piers** Mechanical Box Seal **Foundation Repair** Pool Stake Out & Pool Doc Box Set Up Mechanical Air Make Up Foundation Steel - Survey Verified **Deck Steel / Pool Steel** Mechanical Final **Hurricane Strapping – Exterior Wall** Deck Final / Pool Final **Mechanical Change Out Wall Board Exterior Roof Final** Mechanical Cover (Wine Room) Ridge Height - Verification Synthetic Turf Mechanical Final (Wine Room) Stair Compliance **Electrical T-Pole** Sewer Disconnect **Framing Only Electrical Cover Plumbing Water Line** Frame Cover **Electrical Ditch Cover Plumbing Sewer Line Poly Seal Electrical TCI Plumbing Ground** Insulation **Electrical Reconnect** Plumbing Shower Pan/Wall Board Wall Board Interior **Pool Electrical Underground** Plumb Gas: House / Pool / Generator **Brick Tie Pool Electrical Cover Plumbing Cover** Stucco Lathe **Pool Electrical Final Plumbing Final Building Final Electrical Final Pool Plumbing Cover Tree Final** Pool Plumbing Vacuum Breaker, P-Trap **Temporary Drainage** Driveway / Steel **Drainage Partial Plumbing Pool Final Driveway Final Drainage Cover** Water Heater Final Sidewalk/Flatwork/Pavers Steel **Drainage Final** Irrigation Trench / Final Sidewalk/Flatwork/Paver Final Fire Sprinkler Cover / Final Other/Miscellaneous PASS FAIL CONTRACTOR NAME: Saul Cocto DATE: CONTACT PHONE/EMAIL: # 13.542.1448

NSPECTOR COMMENTS: KING Sequiles LLC	J. d. D. 1119	
	INSPECTOR: Jose 6	
	Re-Inspection Fee Required	