## REQUEST FOR INSPECTION CALL DATE: 9/12/23 TIME : \_\_\_\_\_ AM / PM PROPERTY ADDRESS: 11202 Smithdale Rd PERMIT NUMBER:# 19638 **INSPECTOR** □ Bob Baldwin □ Jason Bienek □ Cary Moran □ Jose Gomez ☑ City Engineer <u>Cole</u> Demolition **Generator Concrete Steel Pad Mechanical Cover Temporary Tree Protection Generator Final - Operative** Mechanical Vent Hood **Fencing Pre-Construction Site** Fence Post Hole Mechanical Grill Seal **Piers** Fence Final Mechanical Box Seal **Foundation Repair** Pool Stake Out & Pool Doc Box Set Up Mechanical Air Make Up Foundation Steel - Survey Verified Deck Steel / Pool Steel Mechanical Final Hurricane Strapping - Exterior Wall Deck Final / Pool Final **Mechanical Change Out Wall Board Exterior Roof Final** Mechanical Cover (Wine Room) Ridge Height - Verification Synthetic Turf Mechanical Final (Wine Room) **Stair Compliance Electrical T-Pole Sewer Disconnect** Framing Only **Electrical Cover Plumbing Water Line** Frame Cover **Electrical Ditch Cover Plumbing Sewer Line Electrical TCI** Poly Seal **Plumbing Ground** Insulation **Electrical Reconnect** Plumbing Shower Pan/Wall Board Wall Board Interior **Pool Electrical Underground** Plumb Gas: House / Pool / Generator **Brick Tie Pool Electrical Cover Plumbing Cover** Stucco Lathe **Pool Electrical Final Plumbing Final Building Final Electrical Final Pool Plumbing Cover** Tree Final **Temporary Drainage** Pool Plumbing Vacuum Breaker, P-Trap Driveway / Steel **Drainage Partial Plumbing Pool Final Driveway Final** Drainage Cover **Water Heater Final** Sidewalk/Flatwork/Pavers Steel **Drainage Final** Irrigation Trench / Final Sidewalk/Flatwork/Paver Final Fire Sprinkler Cover / Final Other/Miscellaneous CONTRACTOR NAME: Mike Smith PASS **FAIL** CONTACT PHONE/EMAIL: # 936 . 525 0866 DATE: INSPECTOR COMMENTS: MUSCO Plumbing 7:00 TIME: INSPECTOR: Storm Slewer Cover Re-Inspection Fee Required OK to cover as marked on plans.